

















Instrukcja Montażu

profim


ASSEMBLY INSTRUCTION - UPdown (linging parts)
 MONTAGEANLEITUNG - UPdown (Reihenverbinder)
 INSTRUKCE K MONTÁŽI - UPdown (konektory)
 INSTRUCTION DU MONTAGE - UPdown (connecteurs)
 ИНСТРУКЦИЯ ПО СБОРКЕ - UPdown (соединителя)

UPdown
 (łączniki)



A 2x 	 10	 11	 12	
	 20	 2L	 2R	 B10
	 C40	 C41	 C42	 C43
B 4x  M043	 C10		 C20	

1





A





2x


2





A



2




4x





B


3



1




1



2

4x



B